

EISA PRODUCT REPLACEMENT GUIDE

General Service Fluorescents (2009 Update GSFL)

Replacement Guide

The products affected by the Energy Independent and Security Act of 2007 under the 2009 update are listed in the first column below in **RED**. Bulbrite is proud to offer a full line of compliant halogen, compact fluorescent and LED replacements listed in the columns to the right of the affected lamps. All replacement lamps are recommended based on the closest lumen output to the affected lamps.

AFFECTED LAMPS				REPLACEMENT OPTIONS											
4-Foot ≥ 25W	Item #	Lumen	Impact Date:	STANDARD FLUORESCENTS	Item #	Lumen	CATALOG Page #	REDUCED WATTAGE	Item #	Lumen	CATALOG Page #	HIGH LUMEN	Item #	Lumen	CATALOG Page #
F32T8/730/EW	528032	2750	7/14/2012	F32T8/830/EW	528532	2950	130	N/A			N/A				
F32T8/735/EW	528132			F32T8/835/EW	528632			F28T8/835/EW	528128	2725	131	F32T8/835/HL	529632	3300	131
F32T8/741/EW	528232			F32T8/841/EW	528732			F28T8/841/EW	528228			F32T8/841/HL	529732	3300	
F32T8/750/EW	528332			F32T8/850/EW	528832			N/A			F32T8/850/HL	529832	3200		
4-Foot Miniature Bipin Standard Output ≥ 26W	Item #	Lumen	Impact Date:	STANDARD FLUORESCENTS	Item #	Lumen	CATALOG Page #	REDUCED WATTAGE	Item #	Lumen	CATALOG Page #	HIGH LUMEN	Item #	Lumen	CATALOG Page #
F28T4/30K	585028	2200	7/14/2012	N/A			N/A			N/A					
F28T4/41K	585128														
F28T4/64K	585228														

This lamp will no longer be manufactured after the listed impact date according to the 2007 Energy Independence and Security Act.

